

2/4





FIG. 2

3/4



FUSE C[0]	FUSE C[1]	TRIM CONTROL	VOUT SETTING
NO - CUT	NO - CUT	DC[0]=1, OTHERS=0	BASE
NO - CUT	CUT	DC[1]=1, OTHERS=0	DECREASE
CUT	NO - CUT	DC[2]=1, OTHERS=0	INCREASE
CUT	CUT	DC[3]=1, OTHERS=0	MORE INCREASE

4/4

FIG. 4

